


## 'Squeeking'/'Ringy' MV-69x or M-582.

\*I have MV-69x or M-582, but with several capsules it squeekes and no real signal is present. What's wrong?

I had a M-582 which had this with a M-71. And after upgrading two MV-692 they also had this phenomenon. A friend-technician pointed out the problem with the M-582 and the M-71.

I should bend the rounded electrode-wire a little up so it makes good contact. That solved the issue for my M-582. Luckily!

Few months later two MV-692 had the problem too. I tried several things, but then I remembered the fact with the M-582. Bend the rounded wire a little up (use a small watch-makers-screwdriver) and your set to go again!



Check the technicians page at [technical.raysaudio.com](http://technical.raysaudio.com).